

Category	Brand	Model	Link
AC Adapter	Bellkin	12Vto24V	https://jestineyong.com/belkin-car-usb-charger-repaired/
AC Adapter	Britelite	CTSA-3.0-200SE	https://jestineyong.com/crude-drawing-to-find-out-burnt-components-part-number/
AC Adapter	Chinese	65W-TS03	https://jestineyong.com/ac-dc-adapter-led-on-but-does-not-take-load/
AC Adapter	ERD	TC-70	https://jestineyong.com/open-smmps-transformer-hand-wound-in-mobile-charger-tc-70/
AC Adapter	F&D	F100	https://jestineyong.com/restored-an-fd-usb-video-player-ac-adapter-model-f100/
AC Adapter	Huan	Q1U	https://jestineyong.com/ac-power-adapter-repaired/
AC Adapter	Key	7150	https://jestineyong.com/servicing-laptop-adapter-key-model-7150/
AC Adapter	LG	ADS-18F5G-19	https://jestineyong.com/burnt-jumper-wire-in-power-supply-caused-lg-monitor-to-go-dead/
AC Adapter	LG	WPA-W12W	https://jestineyong.com/bulged-caps-and-bad-smd-pwm-found-in-two-dead-lg-12v-adapters/
AC Adapter	Maxx	1250	https://jestineyong.com/explosive-failure-of-a-maxx-ac-adapter-model-1250/
AC Adapter	Nagano	SQ15W5P-11	https://jestineyong.com/two-resistors-found-open-in-5v-3a-ac-dc-power-adapter/
AC Adapter	ShenZhen	FM-120005-EU	https://jestineyong.com/servicing-12-volt-smmps-adapter/
AC Adapter	Various		https://jestineyong.com/two-ac-adapters-were-saved-from-dump/
Amplifier	Ahuja	A25	https://jestineyong.com/antique-ahuja-valve-power-amplifier-model-a-25-restored/
Amplifier	Ahuja	ASE-32B	https://jestineyong.com/restoring-and-refurbishing-antique-ahuja-ase32b-tube-power-amp/
Amplifier	Ahuja	DPA770	https://jestineyong.com/restored-a-liquid-seepage-spoiled-ahuja-power-amp-model-dpa770/
Amplifier	Ahuja	SSB-60M	https://jestineyong.com/noisy-pots-replaced-in-ahuja-public-address-system-model-ssb-60m/
Amplifier	Ahuja	TM-50	https://jestineyong.com/restoring-antique-valve-amplifier-ahuja-tm-50/
Amplifier	Akai	SS803S	https://jestineyong.com/servicing-akai-active-surround-speaker-system-model-ss803s/
Amplifier	Akai	SS-803-W	https://jestineyong.com/lightning-struck-akai-active-surround-system-restored/
Amplifier	AudioSource	AMP ONE	https://jestineyong.com/servicing-audiosource-amplifier/
Amplifier	AudioSource	AMP ONE	https://jestineyong.com/revisit-of-jinxed-amp-with-torroid-transformer-failure/
Amplifier	Bouyer	AS30	https://jestineyong.com/bouyer-as30-power-amplifier-repair/
Amplifier	ECL82	Valve Amp	https://jestineyong.com/made-an-ecl82-output-vacuum-tube-tester/
Amplifier	Frontech	Multimedia	https://jestineyong.com/servicing-frontech-multimedia-speakers/
Amplifier	Grundig	SV2000	https://jestineyong.com/restored-grundig-sv2000-amplifier/
Amplifier	Intex	2600W	https://jestineyong.com/servicing-intex-multimedia-speaker/
Amplifier	Local Assembly	5.1 Spkr	https://jestineyong.com/found-failures-of-two-audio-output-ics-in-locally-assembled-5-1-speaker-system/
Amplifier	Marantz	PM-25	https://jestineyong.com/fuse-blowing-in-marantz-pm-25-amplifier-resolved/
Amplifier	Marantz	SM500DC	https://jestineyong.com/marantz-amplifier-repaired/
Amplifier	NAD	C300	https://jestineyong.com/shorted-mosfets-and-bad-capacitors-in-amplifier/
Amplifier	NAD	C300	https://jestineyong.com/broken-diode-and-shorted-tantalum-capacitor-found-in-nad-c300-amplifier/
Amplifier	Norge	2060	https://jestineyong.com/fuse-blown-and-power-on-led-found-short-in-norge-2060-amplifier/
Amplifier	Philips	22AH393	https://jestineyong.com/provided-speaker-protection-circuit-in-philips-amplifier-22ah393/
Amplifier	Philips	DH898	https://jestineyong.com/fabricating-bracket-and-altering-speaker-connections-in-philips-amp/
Amplifier	Philips	SP-120	https://jestineyong.com/blown-lcd-lamps-replaced/
Amplifier	Pioneer	SA610	https://jestineyong.com/original-eight-pin-volume-control-replaced-in-pioneer-amp-model-no-sa610/
Amplifier	QED	A240	https://jestineyong.com/left-channel-output-found-charred-in-qued-a240cd-amplifier/
Amplifier	Sansui	AU-D5	https://jestineyong.com/sansui-au-d5-integrated-amplifier-repair/
Amplifier	Self Made	STK-407-070B	https://jestineyong.com/birth-of-a-good-amplifier-from-the-junkyard/
Amplifier	Self Made	STK-4141	https://jestineyong.com/stk-ic-tester/
Amplifier	Self Made	STK-435	https://jestineyong.com/how-to-build-stk435-amplifier-ic-tester/
Amplifier	Sonodyne	SC-1020	https://jestineyong.com/tampered-amplifier-set-repaired/
Amplifier	Sony	TA-V10	https://jestineyong.com/servicing-sony-ta-v10-amplifier/
Amplifier	Unisound	UB-50	https://jestineyong.com/servicing-unisound-ub-50-public-address-system/
Amplifier	Yamaha	AX-530	https://jestineyong.com/servicing-yamaha-amp-ax-530/
Assembled Extn Box	Self Made	Assembled	https://jestineyong.com/do-it-yourself-diy-ac-extension-box/
Audio Mixer	Sound Craft	EPM8	https://jestineyong.com/rescue-of-a-sound-craft-mixer-epm8/
Bladeless FAN	Nameless	Nil	https://jestineyong.com/swing-motor-shaft-exchanged-and-modified-in-a-nameless-bladeless-fan/
Car Audio	Iden	Nil	https://jestineyong.com/dirty-strip-wire-caused-freezing-of-iden-car-stereo/

Car Audio	Sony	CDX-GT44U	https://jestineyong.com/micro-switch-found-short-in-sony-car-stereo/
Car Audio	Sony	WX-GT88UI	https://jestineyong.com/funny-tuner-ic-complaint-found-in-sony-car-cd-player/
Car Audio	Ultrasonic	US-CDM-8884BT	https://jestineyong.com/cockroach-eggs-caused-this-ultrasonic-car-stereo-to-become-dead/
Cassette Deck	Bang & Olufsen	Beocord9000	https://jestineyong.com/defective-and-discontinued-microcontroller-functions-bypassed-in-bang-olufsen-tape-deck/
Cassette Deck	BIC	T.1	https://jestineyong.com/just-replacement-of-hall-sensor-belt-solved-running-problems-in-bic-cassette-deck-t-1/
Cassette Deck	Fairmate	CS650	https://jestineyong.com/servicing-fairmate-cs650-tape-recorder/
Cassette Deck	Ferguson	FTR-100	https://jestineyong.com/revived-antique-tape-recorder-ferguson-ftr-100/
Cassette Deck	Harman Kardon	HK300XM	https://jestineyong.com/overhauling-mechanism-of-harman-kardon-cassette-deck-hk300xm/
Cassette Deck	NAD	6100	https://jestineyong.com/putting-double-belt-resolved-a-perennial-problem-in-nad6100-tape-deck/
Cassette Deck	Nakamichi	ZX-7	https://jestineyong.com/fully-leaked-capacitors-found-in-nakamichi-tape-deck/
Cassette Deck	Panasonic	RQ212S	https://jestineyong.com/saved-an-antique-panasonic-walkman-and-fixed-its-broken-eject-door/
Cassette Deck	Philips	15AM354-20R	https://jestineyong.com/broken-gear-wheel-and-worn-out-sliding-pots-found-in-an-antique-philips-cassette-player/
Cassette Deck	Philips	AW-529	https://jestineyong.com/philips-cassette-deck-aw529-restored/
Cassette Deck	Sony	TC-158SD & TC-520S	https://jestineyong.com/restoring-two-antique-sony-tape-recorders/
Cassette Deck	Teac	A500	https://jestineyong.com/teac-a500-stereo-cassette-deck-repair/
Cassette Deck	Teac	A500	https://jestineyong.com/servicing-teac-a500-stereo-deck/
Cassette Deck	Technics	RS-B305	https://jestineyong.com/no-play-in-technics-rs-b305-tape-deck-solved/
Cassette Deck	Technics	RS-M85-MK2	https://jestineyong.com/servicing-technics-rs-m85-mk2-tape-deck/
Cassette Deck	Technics	RS-TR333	https://jestineyong.com/do-you-have-a-gear-wheel-broken-technics-rs-tr333-tape-deck-here-is-the-solution/
Cassette Deck	Yamaha	TC520	https://jestineyong.com/no-cassette-play-in-yamaha-tc-520-cassette-deck-resolved/
Cassette Deck	Yamaha	TC-520	https://jestineyong.com/servicing-yamaha-tc520-tape-deck/
Cassette Deck Amplifier	Sonodyne	SCR-2065	https://jestineyong.com/sonodyne-scr2065-brought-back-to-life/
Cassette Deck Amplifier	Sony	TC-520CS	https://jestineyong.com/smart-wasp-in-antique-sony-tape-recorder-tc-520cs/
CD/DVD Player	Cambridge	Azur-540C	https://jestineyong.com/toroidal-transformer-failed-in-cambridge-dvd-player/
CD/DVD Player	Cambridge	Azur-540C	https://jestineyong.com/rusted-and-corroded-crystal-oscillators-found-in-cambridge-audio-azur-540c/
CD/DVD Player	Cambridge	CD6	https://jestineyong.com/customer-demanded-replacement-of-all-caps-in-cambridge-cd-player-cd6/
CD/DVD Player	Elekta	EDVIX-740MIC	https://jestineyong.com/innovative-modification-in-servicing-of-electa-dvd-player-model-edvix-740mic/
CD/DVD Player	First 1	FDIVX-316	https://jestineyong.com/how-to-repair-no-power-fault-in-dvd-player/
CD/DVD Player	iBell	IBL3288	https://jestineyong.com/defective-smps-ttransformer-chopper-found-in-ibell-dvd-player-model-ibl3288/
CD/DVD Player	iBell	IBL3288	https://jestineyong.com/fungus-attacked-smps-and-defective-loading-motor-found-in-ibell-ibl3288-dvd-player/
CD/DVD Player	Igold	IGL-DV05	https://jestineyong.com/burst-capacitor-and-bad-strip-wire-found-in-igold-dvd-player/
CD/DVD Player	Impex	Prime HD	https://jestineyong.com/dropped-value-and-burst-capacitors-found-in-impex-dvd-player-prime-hd/
CD/DVD Player	OKMC	KM15	https://jestineyong.com/open-run-dc-resistor-caused-power-supply-failure-in-dvd-player/
CD/DVD Player	Onida	DFX-8520	https://jestineyong.com/bad-capacitors-and-eye-unit-found-in-onida-dvd-player/
CD/DVD Player	Onix	Grand A	https://jestineyong.com/loading-tray-in-out-problem-in-onix-dvd/
CD/DVD Player	Panasonic	DVD-S2	https://jestineyong.com/failed-smps-revived-with-module-and-amp-added-in-panasonic-dvd-player-model-dvd-s2/
CD/DVD Player	Panasonic	DVD-S45	https://jestineyong.com/burst-pwm-ic-and-caps-found-in-panasonic-dvd-player/
CD/DVD Player	Panasonic	SA-PT860	https://jestineyong.com/complex-circuit-of-panasonic-surround-system-sa-pt860-and-tips-for-troubleshooting/
CD/DVD Player	Philips	DVD625K	https://jestineyong.com/intermittent-on-off-problems-solved-in-philips-dvd-player-model-dvd625k-691/
CD/DVD Player	Philips	DVP3068/94	https://jestineyong.com/replacing-motherboard-in-philips-dvp3068-94/
CD/DVD Player	Philips	DVP3608/94	https://jestineyong.com/no-disc-error-dvd-player/
CD/DVD Player	Philips	HT-155DD	https://jestineyong.com/servicing-lg-dvd-home-theatre-model-ht-155dd/
CD/DVD Player	Philips	PET816/98	https://jestineyong.com/servicing-philips-pet81698-dvd-player/
CD/DVD Player	Pigeon	DVD-CLEAR	https://jestineyong.com/no-power-in-pigeon-dvd-player-solved-and-defective-eye-unit-replaced/
CD/DVD Player	Sony	DVP-SR650P	https://jestineyong.com/dead-sony-dvd-player-brought-back-to-life/
CD/DVD Player	Vinverth	VGDP-3218	https://jestineyong.com/dvd-player-no-eject-problem-solved/
Component System	JVC	MX-J170V	https://jestineyong.com/restoration-of-jvc-mx-j170v-component-system/
Component System	Sony	RV-5	https://jestineyong.com/fixing-blue-tooth-usb-fm-module-in-sony-component-system-rv-5/
Component System	Zen	ZMS-7LCD	https://jestineyong.com/dead-zen-micro-hifi-lcd-component-system-solved/
Computer	Local Assembly	Assembled	https://jestineyong.com/computer-motherboard-restored-after-its-vga-connector-got-ripped-off/
CRT TV	BPL	FHR-9307	https://jestineyong.com/more-than-170-components-replaced-in-bpl-fhr-9307-crt-tv-to-bring-it-back-to-life/

CRT TV	BPL	LFR20FA1	https://jestineyong.com/no-picture-with-violet-raster-and-no-response-to-controls-solved-in-bpl-crt-tv/
CRT TV	Chinese	China Kit	https://jestineyong.com/fixing-es-china-kit-in-crt-tv/
CRT TV	Daewoo	AB21-FTS	https://jestineyong.com/repeated-failure-of-fbt-in-crt-tv-solved/
CRT TV	Daewoo	AB21-FTS	https://jestineyong.com/no-power-bursting-of-optoisolator-ic-in-tv-repaired/
CRT TV	Grundig	T21-324	https://jestineyong.com/grundig-tv-repair-tips-china-kit-and-rejuvenation/
CRT TV	JVC	China Kit	https://jestineyong.com/servicing-crt-tv-mainboard-with-china-kit/
CRT TV	LG	21FA2AG-A9	https://jestineyong.com/escaped-from-a-potential-fire-hazard-in-lg-crt-tv/
CRT TV	LG	21FU3AG3AZ	https://jestineyong.com/longer-time-to-get-on-in-lg-crt-tv-solved/
CRT TV	LG	Flatron	https://jestineyong.com/crt-tv-repair-flyback-replaced/
CRT TV	LG	Flatron	https://jestineyong.com/crt-rejuvenation-in-lg-crt-tv-flatron-plus/
CRT TV	Nikai	NTV2102	https://jestineyong.com/dead-crt-tv-brought-back-to-life-and-how-it-snubbed-my-nose/
CRT TV	Onida	CO21BLL250BG	https://jestineyong.com/both-speakers-found-open-in-onida-crt-tv/
CRT TV	Onida	CO21ESP300BU	https://jestineyong.com/lightning-strikes-on-onida-ultraslim-300-tv/
CRT TV	Onida	CO21SBL300B	https://jestineyong.com/cracked-fuse-capacitor-shorted-str-diodes-found-in-onida-ultra-slim-crt-tv/
CRT TV	Onida	CO21SJG350BR	https://jestineyong.com/leaky-capacitor-caused-onida-crt-tv-to-become-dead/
CRT TV	Onida	CO21SJQ350BR	https://jestineyong.com/vdr-saved-onida-ultra-slim-crt-tv-model-co21sjq350br-from-extensive-damage-by-lightning/
CRT TV	Onida	Slim 300	https://jestineyong.com/servicing-onida-slim-300-crt-tv/
CRT TV	Onida	Slim 300	https://jestineyong.com/this-crt-tv-took-another-blow-but-restored-onia-ultra-slim-co21sbl300b/
CRT TV	Optonica	CS-5151A	https://jestineyong.com/smtps-transformer-failed-in-optonica-cs-5151a-crt-tv/
CRT TV	Panasonic	TC-21FJ20C	https://jestineyong.com/sabotage-done-by-a-jealous-technician-solved-in-crt-tv/
CRT TV	Panasonic	TC-21FX21C3	https://jestineyong.com/dead-panasonic-tc-21fx21c3-crt-ctv-repaired/
CRT TV	Panasonic	TC-21FX21C3	https://jestineyong.com/peak-atlas-showed-silicon-h-out-transistor-as-germanium-in-panasonic-ctv/
CRT TV	Philips	14PT2004/94R	https://jestineyong.com/lightning-damages-micro-controller-ic-in-philips-14-crt-tv/
CRT TV	Philips	20GX1553/94R	https://jestineyong.com/burst-capacitor-and-cracked-dry-solder-found-in-philips-crt-tv/
CRT TV	Philips	20-GX-1553/94R	https://jestineyong.com/burst-x-type-capacitor-caused-tv-go-dead-in-philips-crt-tv/
CRT TV	Philips	21PT3525/V7	https://jestineyong.com/servicing-philips-ctv/
CRT TV	Philips	21PT3525/V7	https://jestineyong.com/shorted-diode-and-bulged-capacitor-in-philips-crt-tv-repaired/
CRT TV	Rising	TV-509	https://jestineyong.com/servicing-rising-model-no-tv-509-5-5-crt-tv-monochrome/
CRT TV	Samsung	CB20E4V2X	https://jestineyong.com/restoration-of-a-samsung-crt-tv-by-rejuvenating-crt/
CRT TV	Samsung	CB20-F4	https://jestineyong.com/video-missing-in-samsung-crt-solved/
CRT TV	Samsung	CD20F4	https://jestineyong.com/burnt-and-badly-leaked-capacitor-found-in-samsung-crt-tv/
CRT TV	Samsung	China Kit	https://jestineyong.com/beware-of-duplicate-yokes-of-crt-tv/
CRT TV	Samsung	China Kit	https://jestineyong.com/horizontal-output-transistor-failed-in-samsung-crt-tv-with-china-kit/
CRT TV	Samsung	CS21C370FL	https://jestineyong.com/fbt-found-failed-in-samsung-crt-tv-tips-and-tricks-for-troubleshooting-crt-tvs/
CRT TV	Samsung	KS9A21M16	https://jestineyong.com/rejuvenated-a-weak-crt-tube-of-samsung-model-ks9a21m16-and-fixed-broken-back-cover/
CRT TV	Sansui	SY21	https://jestineyong.com/leaked-and-rusted-e-cap-found-in-sansui-tv/
CRT TV	Sansui	SY21	https://jestineyong.com/burst-capacitor-and-vertical-failure-in-tv-after-lightning-strike/
CRT TV	Sharp	20C-N1	https://jestineyong.com/track-served-as-a-fuse-to-save-crt-tv-from-lightning/
CRT TV	Sharp	21FX300	https://jestineyong.com/track-leak-under-smd-resistor-found-in-sharp-crt-tv-model-21fx300/
CRT TV	Sharp	21RK21N	https://jestineyong.com/jerking-and-vanishing-osd-in-sharp-21rk21n-crt-tv/
CRT TV	Sharp	51EN7	https://jestineyong.com/crt-tube-replacement-and-total-restoration-of-sharp-ctv-51en7/
CRT TV	Sharp	China Kit	https://jestineyong.com/burst-fbt-found-in-21-crt-tv-with-china-kit/
CRT TV	Sony	KV-G21PD1	https://jestineyong.com/complex-servicing-of-sony-crt-tv-with-tips-tricks-for-easy-troubleshooting/
CRT TV	Supra	China Kit	https://jestineyong.com/smtps-transformer-live-tester-and-servicing-crt-tv/
CRT TV	Supra	ST21K33F	https://jestineyong.com/transplanting-keys-in-crt-tv-repair-model-supra-st21k33f/
CRT TV	TN Government	CTVTN14	https://jestineyong.com/flyback-arcng-and-burnt-crt-base-pcb-found-in-14-crt-tv/
CRT TV	Toshiba	China Kit	https://jestineyong.com/restoring-a-crt-tv-with-philips-china-kit/
CRT TV	Vertical IC Tester	Assembled	https://jestineyong.com/instant-make-vertical-ic-checker/
CRT TV	Videocon	CTV22NP	https://jestineyong.com/intermittent-on-off-problem-in-videocon-crt-tv-ctv22np-solved/
Emergency Light	Chinese	Collapsible	https://jestineyong.com/servicing-collapsible-solar-lantern/
Emergency Light	Chinese	DP30	https://jestineyong.com/how-to-service-dp-30-led-emergency-lamp/

Emergency Light	Chinese	Retrofit	https://jestineyong.com/servicing-chinese-retro-lantern/
Emergency Light	ClickOn	CK5060	https://jestineyong.com/new-clickon-emergency-led-light-with-battery-management-ic-goes-dead/
Emergency Light	Mr.Light	Mr.X10	https://jestineyong.com/dry-solder-caused-no-light-in-mr-light-emergency-light/
Emergency Light	Mr.Light	Mr680VR	https://jestineyong.com/restoring-mr-light-mr-680v6-emergency-light/
Emergency Light	Orkia	22LED	https://jestineyong.com/burst-capacitor-found-in-transformerless-orkia-22-led-emergency-light/
Fan Regulators	Havells	Nil	https://jestineyong.com/four-havells-electronic-fan-regulators-brought-back-to-life/
Induction Cooker	Adeli	AL-2000A1	https://jestineyong.com/e2-error-solved-in-adeli-induction-cooker-model-no-al2000-a1/
Induction Cooker	Avon	VQ16	https://jestineyong.com/no-heating-in-avon-induction-cooker-vq16-solved/
Induction Cooker	Butterfly	Premium	https://jestineyong.com/induction-cooker-repair/
Induction Cooker	Butterfly	Premium	https://jestineyong.com/e03-error-in-butterfly-premium-induction-cooker/
Induction Cooker	Butterfly	Premium	https://jestineyong.com/burst-capacitor-found-in-prestige-induction-cooker/
Induction Cooker	Butterfly	Premium	https://jestineyong.com/failure-of-a-new-induction-cooker-board-resulted-in-restoration-of-butterfly-model-premium/
Induction Cooker	Butterfly	RHINO	https://jestineyong.com/bridge-rectifier-and-igbt-found-blown-in-butterfly-induction-cooker-model-rhino/
Induction Cooker	Butterfly	RHINO	https://jestineyong.com/ignoring-techie-friends-advice-caused-return-of-butterfly-induction-cooker-model-rhino/
Induction Cooker	Crompton Greaves	EIC2	https://jestineyong.com/burnt-mains-cord-connector-found-in-crompton-greaves-induction-cooker-model-eic2/
Induction Cooker	E-Cook	US20TP	https://jestineyong.com/wires-found-just-twisted-and-joined-in-e-cook-induction-cooker-model-us-20tp/
Induction Cooker	E-Cook	US2K	https://jestineyong.com/servicing-e-cook-induction-cooker-model-us2k/
Induction Cooker	Ikon	PC-20E-G	https://jestineyong.com/conventional-method-employed-had-to-be-reverted-in-ikon-induction-cooker-service/
Induction Cooker	Impex	IX-R20	https://jestineyong.com/servicing-impex-induction-cooker-model-ix-r20/
Induction Cooker	Impex	Omega-H5	https://jestineyong.com/igbt-found-blown-in-impex-induction-cooker/
Induction Cooker	Impex	Omega-H5	https://jestineyong.com/e6-error-in-impex-induction-cooker-solved/
Induction Cooker	Impex	Omega-H5	https://jestineyong.com/power-flickering-caused-igbt-failure-in-impex-omega-h-5-induction-cooker/
Induction Cooker	Impex	Omega-H5	https://jestineyong.com/frequent-failure-of-igbt-in-impex-omega-h5/
Induction Cooker	New Board		https://jestineyong.com/power-supply-failure-found-in-new-induction-cooker-board/
Induction Cooker	Prestige	PIC 1.0V	https://jestineyong.com/high-voltage-or-lightning-caused-pwm-ic-burst-in-prestige-induction-cooker/
Induction Cooker	Prestige	Premium	https://jestineyong.com/caution-never-keep-one-induction-cooker-on-another-for-testing-a-lesson-learnt/
Induction Cooker	Star	DZ18-TA-0111	https://jestineyong.com/rusted-and-almost-ruined-star-induction-cooker-revived-successfully/
Induction Cooker	TCL	TCH-2082	https://jestineyong.com/terminals-found-in-reverse-order-of-a-defective-transistor-in-a-rust-ruined-tcl-induction-cooker/
Instruments	PeakAtlass	DCA-55	https://jestineyong.com/leaked-capacitors-caused-dim-display-and-low-battery-indication-in-peak-atlas-dca55/
Instruments	Philips	808/TVT	https://jestineyong.com/servicing-philips-tv-tester-808tv/
Keyboard	Casio	CA-100	https://jestineyong.com/casio-ca-100-tone-bank-keyboard-survived-a-wrong-connection/
Laptop	Lenovo	V570	https://jestineyong.com/my-lenovo-laptop-v570-got-revived-after-a-lightning-strike/
LCD/LED TV	Aftron	AFLCD2470FHD	https://jestineyong.com/burst-capacitors-found-in-aftron-lcd-tv/
LCD/LED TV	Ego	E3211	https://jestineyong.com/track-cutting-solved-a-no-display-problem-in-ego-led-tv-e-3211/
LCD/LED TV	Haier	LE22C430V	https://jestineyong.com/471k-mov-cracked-in-led-tv-repaired/
LCD/LED TV	Haier	E32B900D	https://jestineyong.com/playing-at-100-volume-continuously-tore-the-cone-papers-in-haier-led-tv-model-le32b900d/
LCD/LED TV	Haier	LE22B600	https://jestineyong.com/sudden-power-surge-blew-smps-in-two-haier-led-tvs-model-le22b600/
LCD/LED TV	Haier	LE22M600	https://jestineyong.com/sudden-power-surge-blew-smps-in-two-haier-led-tvs-model-le22b600/
LCD/LED TV	Haier	LE32B9000	https://jestineyong.com/bad-smd-capacitor-caused-no-display-in-haier-led-tv-model-le32b9000/
LCD/LED TV	Haier	LE32M600C	https://jestineyong.com/four-different-cases-of-backlight-issues/
LCD/LED TV	Haier	LE39B9000	https://jestineyong.com/backlight-issues-in-haier-le39b9000-and-sharp-lc32m300m-solved/
LCD/LED TV	Haier	LED22B600	https://jestineyong.com/yet-another-single-diode-failure-found-in-haier-led-tv/
LCD/LED TV	Haier	LED32B7000	https://jestineyong.com/bulged-capacitors-and-torn-speakers-found-in-haier-led-tv-model-le32b7000/
LCD/LED TV	Impex	Smart 32	https://jestineyong.com/beware-of-panel-broken-cases-when-no-display-tvs-are-taken-up-for-service/
LCD/LED TV	LG	32LF15R	https://jestineyong.com/fungus-attack-and-inverter-ic-failure-found-in-lg-32-lcd-tv/
LCD/LED TV	LG	32LF561D-TF	https://jestineyong.com/backlight-replaced-and-led-driver-bypassed-in-lg-led-tv-model-32lf561d-tf/
LCD/LED TV	LG	32LF561D-TF	https://jestineyong.com/return-of-an-lg-led-tv-with-backlight-problems-after-four-months-of-working/
LCD/LED TV	LG	32LJ542D	https://jestineyong.com/continued-blinking-of-lg-32lj542d-td-resolved-by-software-reloading/
LCD/LED TV	LG	32LN5100	https://jestineyong.com/fitting-a-universal-board-and-inverted-in-lg-tv-model-32ln5100/
LCD/LED TV	LG	42LB6520-TB	https://jestineyong.com/shorted-zener-diodes-caused-no-sound-in-lg42lb6250-tv/
LCD/LED TV	LG	42LF550T	https://jestineyong.com/backlight-replacement-in-42-lg-led-tv-model-42lf550t/

LCD/LED TV	LG	LF550T	https://jestineyong.com/backlight-failure-after-one-and-half-years-in-lg-42lf550t/
LCD/LED TV	LG	RT20LZ50	https://jestineyong.com/lg-lcd-tv-repaired/
LCD/LED TV	Mr.Light	Phantom 32	https://jestineyong.com/mr-light-needed-a-backlight-fix/
LCD/LED TV	Mr.Light	Phantom 32	https://jestineyong.com/repeated-failure-of-backlight-and-panel-bonding-replacement-in-mr-light-led-tv-phantom-32/
LCD/LED TV	Mr.Light	Phantom 32	https://jestineyong.com/loose-contact-in-power-on-button-caused-dead-condition-in-mr-light-phantom-32/
LCD/LED TV	Panasonic	TH-24C400DX	https://jestineyong.com/backlight-replacements-in-two-led-tvs/
LCD/LED TV	Panasonic	TH-24C400DX	https://jestineyong.com/four-different-cases-of-backlight-issues/
LCD/LED TV	Panasonic	TH-32D200DX	https://jestineyong.com/jumping-of-pictures-solved-in-panasonic-led-tv-model-th-32d200dx/
LCD/LED TV	Panasonic	TH40C400D	https://jestineyong.com/replacement-of-edge-led-in-panasonic-th40c400d/
LCD/LED TV	Philips	24PFL3938/V7 A2	https://jestineyong.com/restored-philips-led-tv-fully-water-logged-in-floods/
LCD/LED TV	Philips	43PUT6002/56	https://jestineyong.com/backlight-issue-and-jumping-image-problems-resolved-in-philips-43put6002-56-led-tv/
LCD/LED TV	Samsung	U11 Board	https://jestineyong.com/fit-a-universal-board-and-saved-this-samsung-led-tv-picked-up-from-scrap-yard/
LCD/LED TV	Samsung	UA32K5100AR	https://jestineyong.com/backlight-replacements-in-two-led-tvs/
LCD/LED TV	Sansui	SJXHB02CTF	https://jestineyong.com/yet-another-track-cut-saves-one-more-led-tv-sansui-model-sjx32hb02ctf/
LCD/LED TV	Sharp	LC24E156M	https://jestineyong.com/fixing-universal-board-in-sharp-led-tv-lc24e156m/
LCD/LED TV	Sharp	LC-32LE341M	https://jestineyong.com/unknown-burst-component-bypassed-to-restore-sound-in-sharp-led-tv-model-lc-32le341m/
LCD/LED TV	Sharp	LC32M300M	https://jestineyong.com/backlight-issues-in-haier-le39b900-and-sharp-lc32m300m-solved/
LCD/LED TV	Sony	32EX310	https://jestineyong.com/vgh-voltages-showed-negative-in-sony-lcd-tv-model-32ex310-with-line-bar-on-screen/
LCD/LED TV	Sony	32EX520	https://jestineyong.com/unsatisfactory-attempt-to-restore-panel-problem-in-sony-lcd-tv/
LCD/LED TV	Sony	KDL-40NX650	https://jestineyong.com/replaced-motherboard-in-sony-led-tv-model-kdl-40nx650/
LCD/LED TV	Sony	KDL-40W600B	https://jestineyong.com/changing-backlight-of-thompson-uhd-led-tv-102cm-and-panel-breaking-case-of-sony-kdl-40w600b/
LCD/LED TV	Sony	KDL-42W850A	https://jestineyong.com/six-time-led-blinking-in-sony-bravia-led-tv-model-kdl-42w850a-solved-and-bl-blinking-fixed/
LCD/LED TV	Sony	KDL-43W800C	https://jestineyong.com/no-display-in-sony-led-tv-repaired-solved-by-masking-pins/
LCD/LED TV	Sony	KLV-29P423D	https://jestineyong.com/shorted-cap-in-scalar-board-caused-no-display-in-sony-led-tv-klv-29p423d/
LCD/LED TV	Sony	KLV-32BX300	https://jestineyong.com/panel-replaced-in-sony-bravia-lcd-tv-model-klv-32bx300-after-all-cutting-tricks-failed/
LCD/LED TV	Sony	KLV-32R402A	https://jestineyong.com/replacing-two-resistors-solved-three-blinking-problem-in-sony-led-tv-klv32r402a/
LCD/LED TV	Sony	KLV-32S400A	https://jestineyong.com/t-con-board-ic-complaint-and-backlight-issue-resolved-in-sony-bravia-klv-32s400a/
LCD/LED TV	Sony	KLV-40R472A	https://jestineyong.com/dead-sony-klv-40r472a-lcd-tv-traced-to-faulty-pfc-adaptor-and-brought-back-to-life/
LCD/LED TV	Sony	W60B	https://jestineyong.com/backlight-replacement-in-sony-bravia-led-tv-model-w60b/
LCD/LED TV	Thomson	102CM	https://jestineyong.com/changing-backlight-of-thompson-uhd-led-tv-102cm-and-panel-breaking-case-of-sony-kdl-40w600b/
LCD/LED TV	Toshiba	32PU200E1	https://jestineyong.com/scaler-board-ic-cm501-found-shorted-in-toshiba-led-tv/
LCD/LED TV	Toshiba	32PU200E1	https://jestineyong.com/revisit-of-toshiba-led-tv-model-32pu200e1-after-three-years/
LCD/LED TV	Videocon	LEDVJW32HH-2FA A1	https://jestineyong.com/level-shifter-ics-found-defective-in-videocon-led-tv-model-ledvjw32hh-2fa-a1/
LCD/LED TV	Videocon	TWKC40FH	https://jestineyong.com/four-different-cases-of-backlight-issues/
LCD/LED TV	Videocon	V3218	https://jestineyong.com/futile-attempts-to-resolve-double-image-in-videocon-led-tv-v3218-resulted-in-panel-replacement/
LCD/LED TV	Videocon	V3218	https://jestineyong.com/four-different-cases-of-backlight-issues/
LCD/LED TV	VU	55K160	https://jestineyong.com/stubborn-panel-short-left-unresolved-in-vu-led-tv-55k160gau/
LCD/LED TV	VU	H40D321	https://jestineyong.com/power-supply-backlight-and-scaler-board-ic-failure-solved-in-vu-led-tv/
LED Driver	Chinese	36 LED	https://jestineyong.com/high-voltage-causes-explosion-in-36-led-light/
LED Driver	Chinese	Display	https://jestineyong.com/smps-of-running-display-failed-due-to-defective-pwm-3842-ic/
LED Driver	Chinese	S-25-12	https://jestineyong.com/13007-power-transistor-faulty-diodes-and-a-capacitor-found-in-self-made-led-porch-light/
LED Driver	Eveready	LBT-4FP	https://jestineyong.com/capacitor-fumed-in-eveready-led-batten-model-lbt-4fp/
LED Driver	Kensonic	S-60-12	https://jestineyong.com/12v-5a-led-driver-smps-repaired/
Lights and Lamps	Chinese	48 LED	https://jestineyong.com/servicing-48-led-random-led-light/
Lights and Lamps	Christmas	Blinking light	https://jestineyong.com/servicing-christmas-light/
Lights and Lamps	Electra	Rechargeable	https://jestineyong.com/restored-fungus-spoiled-electra-torch/
Lights and Lamps	Fast Track	Torch	https://jestineyong.com/servicing-fast-track-torch-and-rebuilding-broken-adaptor/
Lights and Lamps	Gate Lamp	Solar	https://jestineyong.com/open-coil-found-in-solar-gate-lamps/
Lights and Lamps	Ikon	Megaray	https://jestineyong.com/servicing-ikon-megaray-torch/
Lights and Lamps	Philips	10W6500K	https://jestineyong.com/intermittent-problem-in-40-led-philips-light-solved/

Lights and Lamps	Veto	12-18W	https://jestineyong.com/restored-a-lovely-led-surface-panel-light/
Massager	Nais	EV297	https://jestineyong.com/defective-motor-found-in-nais-massager-ev297/
Microwave Oven	Daewoo	KQG-868G	https://jestineyong.com/bad-high-voltage-capacitor-in-microwave-oven/
Microwave Oven	LG	MS-1921HE	https://jestineyong.com/how-to-repair-microwave-oven-not-heating/
Microwave Oven	Onida	Power Grill 21	https://jestineyong.com/membrane-keypad-replaced-with-micro-switches-in-onida-microwave-oven/
Mobile Phone	Oppo	F1S	https://jestineyong.com/replacing-volume-control-and-on-off-switch-knobs-in-oppo-f1s-android-phone/
Monitor	Acer	P166HQL	https://jestineyong.com/dead-short-diode-found-in-acer-p66hql-lcd-monitor/
Monitor	Acer	S200HL	https://jestineyong.com/servicing-s200hl-acer-lcd-monitor/
Monitor	AOC	E1660SW	https://jestineyong.com/open-diodes-and-dry-solders-found-in-aoc-lcd-monitor/
Monitor	AOC	TFT15W60PS	https://jestineyong.com/beware-of-these-fake-pwm-ics/
Monitor	Coby	TF TV1524	https://jestineyong.com/servicing-coby-lcd-tv-monitor/
Monitor	Dell	E178WFPc	https://jestineyong.com/servicing-dell-lcd-monitor/
Monitor	HCT	HLD-150MDP	https://jestineyong.com/replacing-lcd-tubes-with-led-strips-in-hct-tv-monitor-model-number-hld-150mdp/
Monitor	LG	500G	https://jestineyong.com/servicing-lg-monitor-model-500g/
Monitor	LG	Flatron	https://jestineyong.com/why-these-three-capacitors-fail-in-many-lg-flatron-led-monitor/
Monitor	LG	Flatron	https://jestineyong.com/capacitors-burst-and-fuse-blown-found-in-lg-led-monitor/
Monitor	LG	LG500G	https://jestineyong.com/jumping-images-and-colours-solved-in-lg-crt-monitor-500g/
Monitor	LG	W1642S-PF	https://jestineyong.com/replacing-three-bulged-caps-saved-an-lg-monitor/
Monitor	LG	W1642S-PF	https://jestineyong.com/power-failed-in-lg-flatron-w1642s-computer-monitor-due-to-burst-capacitors/
Monitor	LG	W-1643C-PF-BTR	https://jestineyong.com/intermittent-in-two-lg-lcd-monitors-repaired/
Monitor	Samsung	632NW	https://jestineyong.com/servicing-samsung-led-monitor-632nw/
Monitor	Samsung	632NW	https://jestineyong.com/servicing-samsung-led-monitor-632nw/
Monitor	Samsung	632NW	https://jestineyong.com/samsung-computer-monitor-saved-from-water-seepage/
Monitor	Samsung	632NW	https://jestineyong.com/restored-a-defective-power-supply-and-motherboard-in-samsung-monitor-632nw/
Monitor	Samsung	632NW	https://jestineyong.com/burnt-motherboard-replaced-in-samsung-led-monitor-632nw/
Monitor	Samsung	LS22CMZKF/XL	https://jestineyong.com/corroded-wire-caused-no-display-in-samsung-monitor/
Monitor	Worldtech	WT-PDT786K/15	https://jestineyong.com/servicing-worldtech-car-reverse-monitor/
Monitor	Zenith	PC56V	https://jestineyong.com/rusted-push-to-on-button-caused-permanent-display-of-menu-in-zenith-crt-monitor-model-56v/
Multimeter	Sunma	YX-3600Treb	https://jestineyong.com/servicing-sunma-yx-3600treb-analogue-multimeter/
Odometer	Pricol	Inventa	https://jestineyong.com/inaccurate-fuel-indication-in-pricol-digital-odometer/
Oscilloscope	VarTech	SS-5020B	https://jestineyong.com/fungus-attach-in-vartech-oscilloscope/
Portable Audio	Chinese	Keyboard	https://jestineyong.com/restored-a-tampered-keyboard-and-made-a-kid-very-happy/
Portable Audio	Chinese	USB/FM Player	https://jestineyong.com/bad-adapter-caused-malfunctioning-of-blue-tooth-usb-fm-player/
Portable Audio	JBL	Flip4	https://jestineyong.com/bulged-and-stuck-lipo-battery-replaced-in-jbl-bluetooth-speaker-flip4/
Portable Audio	Local Assembly	USB/FM Player	https://jestineyong.com/transformer-failed-in-usb-player/
Portable Audio	Portronics	Puresound	https://jestineyong.com/damaged-charging-socket-replaced-in-portronics-puresound/
Power Bank	Romai	10400mAh	https://jestineyong.com/servicing-romai-power-bank-10400mah/
Power Bank	Xiaomi	T10.4	https://jestineyong.com/fake-batteries-found-in-xiaomi-power-bank-t10-4/
Pre-Amp	Yamaha	C-4	https://jestineyong.com/protect-mode-in-yamaha-c4-pre-amp-solved/
Projector	Wzatco	Native1080P	https://jestineyong.com/auto-shut-off-problem-in-wzatco-projector-s02-a-solved/
Radio	Kemai	MD-1800UR	https://jestineyong.com/rusted-components-found-in-kemai-usb-radio-model-md-1800ur/
Radio	Olsenmark	OMR1239	https://jestineyong.com/smd-regulator-ic-found-open-in-olsenmark-omr1239/
Radio	Philips	DL167	https://jestineyong.com/ic-failure-in-philips-radio-dl167/
Radio	Philips	DL167/40	https://jestineyong.com/bad-capacitor-found-in-philips-radio-dl167-40/
Radio	Philips	DL225/60	https://jestineyong.com/restored-a-philips-radio-that-got-spilled-with-dosa-batter/
Radio	Philips	DL-225/60	https://jestineyong.com/defective-ic-caused-no-am-fm-signal-in-philips-radio/
Radio	Philips	Prestige 556	https://jestineyong.com/servicing-four-radios-sony-icf7600aw-philips-rl118-sangean-sg700l-philips-prestige-556/
Radio	Philips	RL118/00	https://jestineyong.com/bad-am-fm-ic-replaced-in-philips-radio/
Radio	Philips	RL118/00	https://jestineyong.com/mains-cord-was-the-culprit-in-this-philips-radio/
Radio	Philips	RL118/00	https://jestineyong.com/servicing-four-radios-sony-icf7600aw-philips-rl118-sangean-sg700l-philips-prestige-556/
Radio	Philips	RL557	https://jestineyong.com/restoring-a-50-year-old-philips-radio/

Radio	Sangean	SG700L	https://jestineyong.com/servicing-four-radios-sony-icf7600aw-philips-rl118-sangean-sg700l-philips-prestige-556/
Radio	Self Made	TA-7642	https://jestineyong.com/nostalgic-and-fascinating-am-radio-from-a-single-chip-ta7642/
Radio	Sony	CXA1238S	https://jestineyong.com/partial-failure-of-sony-am-fm-ic-cxa1238s-found-in-module/
Radio	Sony	ICF-570	https://jestineyong.com/substitute-electronic-on-off-switch-provided-in-sony-radio/
Radio	Sony	ICF7600AW	https://jestineyong.com/servicing-four-radios-sony-icf7600aw-philips-rl118-sangean-sg700l-philips-prestige-556/
Radio	SSBright	SG-SM129D	https://jestineyong.com/repairing-ssbright-sg-sm129d-fmusblin-in-set/
Radio	Sunma	RPS-500	https://jestineyong.com/burst-capacitor-found-in-suns-radio/
Receiver Amplifier	Akai	AA-1020	https://jestineyong.com/shorted-transistors-and-blown-fuses-found-in-akai-tuner-receiver/
Receiver Amplifier	BPL	CWX-69	https://jestineyong.com/lightning-struck-bpl-two-in-one-model-cwx-69-restored/
Receiver Amplifier	Denon	AVR-X500	https://jestineyong.com/protection-mode-in-denon-avr-x500-solved/
Receiver Amplifier	Denon	AVR-X500	https://jestineyong.com/return-of-denon-avr-x500-in-dead-condition/
Receiver Amplifier	Onkyo	HTR-430	https://jestineyong.com/servicing-onkyo-htr-430-av-receiver/
Receiver Amplifier	Philips	AH719	https://jestineyong.com/rejuvenation-of-philips-tuner-amplifier-model-ah719/
Receiver Amplifier	Sony	HST-D40	https://jestineyong.com/defective-graphic-equalizer-led-array-found-in-sony-stereo-deck-receiver/
Receiver Amplifier	Sony	TA-AV550	https://jestineyong.com/relay-problem-in-sony-surround-system-solved/
SMPS	Beetel	BT-450R	https://jestineyong.com/found-a-diode-shorted-in-computer-smps/
SMPS	CCTV	BN031	https://jestineyong.com/restored-a-cctv-power-supply-with-a-perfect-output/
SMPS	CCTV	DVR12V	https://jestineyong.com/yet-another-cctv-smps-found-with-tank-capacitor-burst/
SMPS	Chinese	LC-8180FSX	https://jestineyong.com/burst-fixed-capacitor-found-in-primary-of-small-size-computer-smps/
SMPS	CIL-ODYSSEY	450-PA	https://jestineyong.com/several-bad-capacitors-found-in-smps/
SMPS	Delta Elec	DPS-250AB-22	https://jestineyong.com/two-smps-saved-from-dump/
SMPS	Dyson Salom	17530-01	https://jestineyong.com/corrosion-caused-repeated-failure-of-pwm-in-battery-charging-smps-dyson-salom-17530-01/
SMPS	Enhance	SFX-200D	https://jestineyong.com/capacitors-found-bulged-in-enhance-smps/
SMPS	Enhance	SFX-200D	https://jestineyong.com/bulgy-capacitors-found-in-enhance-model-computer-smps/
SMPS	Enhance	SFX-200D	https://jestineyong.com/smd-resistor-found-burnt-and-displaced-in-enhance-smps-model-sfx-200d/
SMPS	Foxin	FPS-500	https://jestineyong.com/corroded-wires-caused-intermittent-contacts-in-computer-atx-smps/
SMPS	Foxin	FPS-500C	https://jestineyong.com/dry-solder-caused-foxin-computer-smps-to-go-dead/
SMPS	Foxin	FPS500S	https://jestineyong.com/saving-computer-smps-part-4/
SMPS	Foxin	FPS-500S	https://jestineyong.com/how-to-repair-foxin-atx-power-supplies/
SMPS	Foxin	FPS-500S	https://jestineyong.com/burst-capacitor-and-dry-solder-found-in-foxin-computer-atx-model-fps500s/
SMPS	Frontech	JIL-24141	https://jestineyong.com/servicing-frontech-atx-power-supply/
SMPS	Guard	CPS-88	https://jestineyong.com/one-zener-diode-found-cracked-and-another-shorted-in-cctv-smps/
SMPS	Iball	LPE223-400	https://jestineyong.com/bridge-rectifier-found-open-in-iball-computer-smps/
SMPS	Iball	LPE223-400	https://jestineyong.com/saved-two-more-atx-smps-from-dump/
SMPS	Iball	LPE223-400	https://jestineyong.com/saved-another-computer-smps-from-dump/
SMPS	Iball	SPS-252	https://jestineyong.com/how-to-repair-and-servicing-iball-pc-smps/
SMPS	Intel	Smart IT-2045S+	https://jestineyong.com/14-bad-components-found-in-intex-smps-model-smart-it-2045s-unbelievable/
SMPS	Intex	Smart IT-2045S+	https://jestineyong.com/saved-two-more-atx-smps-from-dump/
SMPS	Intex	Techno	https://jestineyong.com/maintenance-done-in-computer-smps-lasting-for-five-years/
SMPS	Mercury	KEZ-M200	https://jestineyong.com/saving-computer-smps-part-5/
SMPS	Mercury	KOB AP4300XA	https://jestineyong.com/pc-atx-smps-saved-from-dump-with-almost-no-cost-for-repairs/
SMPS	Mercury	KOB AP4400XA	https://jestineyong.com/servicing-mercury-smps-kob-ap4400xa/
SMPS	Priya	450W	https://jestineyong.com/saving-computer-smps-part-4/
SMPS	Red Sea	Pressure Monitor	https://jestineyong.com/cracked-unknown-pwm-replaced-by-universal-module-in-pressure-monitor-smps/
SMPS	Small Size	LC-8180SFX	https://jestineyong.com/servicing-small-size-power-supply-model-lc-8180sfx/
SMPS	SuperComp	SEP500	https://jestineyong.com/replacement-of-two-bulged-capacitors-and-dry-solder-patch-up-brought-life-back-to-smps/
SMPS	SuperComp	SEP500	https://jestineyong.com/fixed-cap-found-cracked-in-supercomp-sep-500-atx-smps/
SMPS	SuperComp	SEP500	https://jestineyong.com/dry-solder-and-dropped-value-of-caps-found-in-atx-smps/
SMPS	SuperComp	SEP500	https://jestineyong.com/no-load-taking-computer-smps-restored/
SMPS	Various		https://jestineyong.com/saving-computer-atx-smps-power-supplies-part-1/
SMPS	Various		https://jestineyong.com/saving-computer-atx-smps-power-supplies-part-2/

SMPS	Various		https://jestineyong.com/saving-computer-smps-part-3/
SMPS	Zebronic	N450W	https://jestineyong.com/just-patching-up-dry-solder-revived-a-dead-zebronic-computer-pc-smps/
SMPS	Zebronic	ZEB-450W	https://jestineyong.com/servicing-zebronic-atx-power-supply/
SMPS	Zebronic	ZEB-450W	https://jestineyong.com/burst-capacitor-and-dry-solder-found-in-zebronic-zeb-450w-smps/
SMPS	Zebronic	ZEB-450W	https://jestineyong.com/two-computers-smps-saved-from-e-waste/
SMPS	Zebronic	ZEB-450W	https://jestineyong.com/saving-computer-smps-part-5/
Telephone	Atlinks	EX26710GE-A	https://jestineyong.com/servicing-ge-atlinks-cordless-phone-base-unit/
Telephone	Pramoda	PT-33P	https://jestineyong.com/lightning-struck-on-telephone-repaired/
Three-in-one	JVC	RC-EX40V	https://jestineyong.com/servicing-and-modifying-jvc-rc-ex40v-three-in-one/
Three-in-one	Philips	AZ1047/94	https://jestineyong.com/partial-restoration-of-philips-three-in-one/
Three-in-one	Philips	AZ1047/94	https://jestineyong.com/tracks-found-cut-in-philips-az1047-94-cd-sound-machine/
Three-in-one	Philips	AZ380	https://jestineyong.com/servicing-philips-cd-sound-machine-az380/
Three-in-one	Philips	AZ380	https://jestineyong.com/rusted-crystal-caused-no-radio-in-philips-cd-player-model-az380-94/
Three-in-one	Philips	AZ380	https://jestineyong.com/dry-solder-and-defective-capacitors-found-in-philips-az380-94/
Three-in-one	Toshiba	TY-CKU300BS	https://jestineyong.com/servicing-toshiba-cd-usb-radio-cassette-recorder/
Timer	Self Made	555	https://jestineyong.com/assembled-a-555-based-timer-for-water-boiler/
Tools	Creationspace	Screw Driver	https://jestineyong.com/rusted-bearing-found-in-creationspace-precision-screwdriver-1pj1802a/
Tools	Dewalt	DCD-950	https://jestineyong.com/fifteen-corroded-batteries-found-in-dewalt-dcd-950-driver-hammer-drill/
Tools	Kada	2018D+	https://jestineyong.com/resolved-op-error-due-to-a-design-problem-in-kada-2018-d-soldering-work-station/
Tools	MetroQ	MTQ4070	https://jestineyong.com/intermittent-problems-in-metroq-mtq4070-lcr-meter-solved/
Tools	OSS Team	T-12X	https://jestineyong.com/neglected-earth-wire-blew-the-mosfet-and-pwm-of-oss-team-soldering-work-station-t-12x/
Tuner	Pioneer	TX-520	https://jestineyong.com/servicing-pioneer-tx-520-tuner/
Turntable	Sansui	P-1000	https://jestineyong.com/dragging-motor-and-loose-belts-replaced-in-sansui-turntable-model-p-1000/
Two-in-One	Akai	AJ500FS	https://jestineyong.com/revived-an-antique-akai-stereo-cassette-recorder-aj-500fs/
Two-in-One	BPL	M9903-3H	https://jestineyong.com/modifying-bpl-m9903-two-in-one-to-house-usb-unit-in-place-of-tape/
Two-in-One	BPL Sanyo	M9903-3H	https://jestineyong.com/voltage-surge-blew-transformer-of-bpl-m9903-h-two-converted-to-three-in-one/
Two-in-One	Grundig	K-RR125	https://jestineyong.com/resolved-two-issues-in-grundig-k-rr125-two-in-one/
Two-in-One	National	RX-C37	https://jestineyong.com/restored-another-antique-national-rx-c37-tape-recorder/
Two-in-One	National	RX-FS21A	https://jestineyong.com/revived-the-radio-pick-up-in-national-rx-fs21a-two-in-one-but-with-a-sad-end/
Two-in-One	National	SG250W	https://jestineyong.com/restored-a-rat-spoiled-national-sg250w-two-in-one/
Two-in-One	National Panasonic	RX-5100	https://jestineyong.com/national-panasonic-rx5100-radio-cassette-repaired/
Two-in-One	National Panasonic	RX-5100F	https://jestineyong.com/fixed-broken-wheel-of-tuning-needle-in-national-panasonic-rx-5100f/
Two-in-One	Panasonic	RX-5055F	https://jestineyong.com/modified-capstan-wheel-base-support-in-panasonic-two-in-one/
Two-in-One	Panasonic	RX-5055F	https://jestineyong.com/repairing-of-speaker-and-change-of-tape-head-done-in-panasonic-rx-5055f-radio-cassette-player/
Two-in-One	Panasonic	RX-CS730	https://jestineyong.com/restoration-and-modification-of-panasonic-rx-cs730-two-in-one/
Two-in-One	Panasonic	RX-M70M2	https://jestineyong.com/return-of-panasonic-rx-m70m2-two-in-one-with-mains-transformer-failure/
Two-in-One	Sanyo	Big-100K	https://jestineyong.com/mud-dauber-wasp-forced-me-to-break-open-sanyo-big-100k-radio-cassette-recorder/
Two-in-One	Sharp	WG-293BZ(BK)	https://jestineyong.com/corroded-tracks-and-bad-capacitors-found-in-sharp-two-in-one/
UPS/Stabilizers/Inverters	Arctic	Auto Cut Off	https://jestineyong.com/shorted-zener-diode-found-in-voltage-stabilizer/
UPS/Stabilizers/Inverters	Crown	Fridge	https://jestineyong.com/dry-solder-and-bad-capacitors-caused-refrigerator-stabilizer-to-go-dead/
UPS/Stabilizers/Inverters	LG	Fridge	https://jestineyong.com/adjustable-shunt-regulator-found-defective-in-lg-fridge-inverter-board/
UPS/Stabilizers/Inverters	Numeric	Digital 600EX	https://jestineyong.com/rusted-transistor-caused-numeric-computer-ups-to-become-dead/
UPS/Stabilizers/Inverters	V-Care	500VA	https://jestineyong.com/silenced-a-chattering-voltage-stabilizer/
UPS/Stabilizers/Inverters	V-Guard	Fridge	https://jestineyong.com/transistor-failed-in-v-guard-stabilizer/
Vaccum Cleaner	BPL-Sanyo	BSC2002	https://jestineyong.com/fixed-a-broken-bpl-sanyo-vacuum-cleaner/
Vaccum Cleaner	Eureka Forbes	EC-300-LD	https://jestineyong.com/shorted-motor-burst-triac-in-eureka-forbes-vacuum-cleaner-euroclean-xl/
Valve Radio	GEC	BC-5746	https://jestineyong.com/lovely-gec-valve-radio-repaired/
Valve Radio	HMV	HMV5231CA	https://jestineyong.com/restoring-amplifier-in-hmv-radiogram-futile-attempt-to-restore-its-radio/
Valve Radio	Kreffft	Valve Radio	https://jestineyong.com/servicing-kreft-valve-radio/
Valve Radio	Kreffft	Valve Radio	https://jestineyong.com/restored-a-tampered-and-spoiled-kreft-valve-radio/
Valve Radio	Philips	15RB/505/00Z	https://jestineyong.com/resurrection-of-a-philips-prestige-valve-radio/

Valve Radio	Philips	15RB/525/11Z	https://jestineyong.com/restoration-of-antique-philips-valve-radio-model-15rb525-11z/
Valve Radio	Philips	15RB708/00S	https://jestineyong.com/restoration-of-an-antique-philips-valve-tube-radio-15rb708-00/
Valve Radio	Philips	Novosonic	https://jestineyong.com/philips-novosonic-valve-radio-restored/
Valve Radio	Sharp	7A57	https://jestineyong.com/restoring-a-sharp-jhankar-tube-radio-7a57/
Valve Radio	UMS/GEC	Various	https://jestineyong.com/servicing-two-valve-radios/
Walkman	Sony	TCM150	https://jestineyong.com/fixed-broken-intricate-parts-in-mechanism-in-sony-walkman-tcm-150/